

# Download 2004 Expedition Abs Light On

Replaced rear rotors and brake pads but the rotors wouldnt come off so i had to take the whole hub off to end up getting them of I finish the whole ...My brake pedal pulses and ABS light is on. Reply 1: That sounds like a false activation caused by an inaccurate wheel speed sensor. Have the ABS codes...Replacing rear abs sensor ...  
1997-2004 Ford F-150 & 1997-2002 Ford Expedition 4WD Front Hub and Bearing Replacement - Duration: 27:05.